

BLADE MOLD REPAIR REPORT
1-29-14

Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Cylinder Reporting Suction Side Post Repair::Suction Root Diameter Post Repair			
	X	Y	Z
Begin	610.7191	-259.0276	-334.5479
End	374.6260	-344.6246	-332.9807
Direction	-0.940101	-0.340839	0.006241
Proj. Ang.	Rx from Y	Ry from Z	Rz from X
(deg.)	178.9511	-89.6197	-160.0716
Radius	206.8110	Diameter	413.6219
Length	251.1359		



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES

Cylinder Root Cyl Pre Repair::Pressure Side Cyl Pre Repair			
	X	Y	Z
Begin	17.1632	3.5740	-0.1491
End	261.2834	5.9155	-1.6221
Radius	204.3998	Diameter	408.7995
Length	244.1359		



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Cylinder Reporting Pressure Side Post Repair::Root Scan			
	X	Y	Z
Begin	1814.7438	-686.5618	-356.5926
End	1960.4917	-519.8760	-359.8522
Direction	0.658172	0.752724	-0.014720
Proj. Ang.	Rx from Y	Ry from Z	Rz from X
(deg.)	-1.1203	91.2812	48.8340
Radius	207.4523	Diameter	414.9046
Length	221.4436		



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES



Notes:

Inspected By : Danny Southerly
Instrument : API RADIAN Laser Tracker
Calibration: 7NOV13
SN : 60030

UNITS: Milli

Title: Blade Mold Pre and Post Repair

Date: 1-29-14

API SERVICES